



- Technical requirements:**
- 1, on the drawing for finished product size, size.
 - 2, the size of the mark is the end product size.
 - 3, mark tolerance is the key control the size of the size.
 - 4, not standard size according to 3 ① production, not standard tolerance table execution

制图 Drawn By	陈东明		深圳亦琦捷电子有限公司	
审核 Verify By	顾龙	1/4	比例 1:1	材质 Material
确认 Apvd. By	李浩天	图号 DRW. NO.	1	单位 Unit
Tolerance Unless Otherwise Specified				
Linear	Angle	品名 PART NAME		
0-5	± 0.05	$\phi - 30^{\circ}$	± 1	SZ-QJ-WJ-CR2032-1-W
5-10	± 0.1	$31-60^{\circ}$	± 1	
10-50	± 0.15	$61-90^{\circ}$	± 1	料号 PART NO.
50-100	± 0.2			SQJ-WJ-CR2032-1-W