

Title of Change:	Discontinuance of product due to closure of 5-inch production line and eliminating chemicals called Hydrazine		
Last Time Buy Date:	19 August 2018		
Last Ship Date:	19 February 2019		
Contact information:	Contact your local ON Semiconductor Sales Office or <pcn.support@onsemi.com></pcn.support@onsemi.com>		
	Customers must notify ON Semiconductor ( <pcn.support@onsemi.com>) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." ON Semiconductor and the customer may negotiate an appropriate End-of-Life.</pcn.support@onsemi.com>		
Description and Purpose:			
ON Semiconductor is publishing thi Hydrazine in ON Semiconductor Ni		ion due to closure of 5-inch pro	oduction line and eliminating chemicals calle
ON Semiconductor wishes to prom appropriately and effectively for re		ntent to exit this small portion	of our overall portfolio so that you may pla
ON Semiconductor has provided a	list of replacement devices, where	available, to aid in this proces	5.
For those devices that have no reco any remaining device inventory.	mmended replacement identified,	, ON Semiconductor has partne	ered with Rochester Electronics who will carr
PLEASE NOTE: ON Semiconductor r this Product Discontinuance becom			ed on inventories available. Also, Devices on
For questions or concerns regardin	g this notification, please contact y	our local sales office or custor	ner service representative.
Additional contacts are: Americas: Tom Siegel (tom.siegel@onsemi.com) ☎ +1 765 868 5022 USA		Europe: Andrej Tomasik (andrej.tomasik@onsemi.com)	
Japan: Isao Usuki (isao.usuki@onsemi.com) 奮 +81 3 5817 1060 Japan		Asia Pacific: Stephen Ng (stephen.ng@onsemi.com) 27 +852 2689 0209 China	
	ORDERS. ACCEPTANCE IS SUBJECT		6) MONTHS FROM THE NOTICE DATE TO NTITIES, PRODUCT AVAILABILITY AND ALL
NOTE: TO ALLOW AN ORDERLY EXI ANNOUNCEMENT DATE.	F FROM THE MARKET, PRODUCT SI	HALL NOT BE DELIVERED AFTEI	R TWELVE (12) MONTHS BEYOND THE
List of Affected Standard Parts	:		
Device to be Discontinu	ed Recommen	ded Replacement	Supplier
LC898200A-TBM-H	LC89	8201TA-NH	ON SEMICONDUCTOR